

Engineering works pattern machine shop, Davy & United Engineering Co. Ltd., Park Iron Works, Sheffield: men are shown working at large machines. Photograph, 1957.

Publication/Creation

1957.

Persistent URL

<https://wellcomecollection.org/works/angmjexn>

License and attribution

This work has been identified as being free of known restrictions under copyright law, including all related and neighbouring rights and is being made available under the Creative Commons, Public Domain Mark.

You can copy, modify, distribute and perform the work, even for commercial purposes, without asking permission.

**wellcome
collection**

Wellcome Collection
183 Euston Road
London NW1 2BE UK
T +44 (0)20 7611 8722
E library@wellcomecollection.org
<https://wellcomecollection.org>

V A series of fourteen photographs showing conditions in the machine shops of Messrs. Dary & United Engineering Co. Ltd., Park Iron Works, Sheffield 4. Showing the conditions respectively fifty and sixty years ago, and in modern times.

© Dary & United Engineering C. L. P.

for F. R. Smith, Publicity Officer 17 Jan 1957



5824281

N.M.M.L.
2271.

Engineering shop conditions in the firm of Davy and United Engineering Company, Ltd., Park Iron Works, Sheffield 4. One of a series of fourteen photographs supplied by Mr. F.R. Smith, Publicity Officer, 17th January, 1957. No. 3026. A modern engineering works pattern shop. Notice the greatly increased head room, the provision of adequate overhead cranes for lifting the heavier patterns, good lighting and spacious conditions for working and also a very efficient dust extraction system which is highly essential in a pattern shop from a health point of view. Compare with No. 4386.

710-13638

FILE PRINT

