

Machining and fitting shop, Davy & United Engineering Co. Ltd., Park Iron Works, Sheffield: men are shown undertaking medium fitting work, in conjunction with machining. Photograph, 1957.

Publication/Creation

1957.

Persistent URL

<https://wellcomecollection.org/works/xk4d8aeg>

License and attribution

This work has been identified as being free of known restrictions under copyright law, including all related and neighbouring rights and is being made available under the Creative Commons, Public Domain Mark.

You can copy, modify, distribute and perform the work, even for commercial purposes, without asking permission.



Wellcome Collection
183 Euston Road
London NW1 2BE UK
T +44 (0)20 7611 8722
E library@wellcomecollection.org
<https://wellcomecollection.org>

Unable to display this page

582447c

W.H.M.L.
2269.

Engineering shop conditions in the firm of Davy and United Engineering Company, Ltd., Park Iron Works, Sheffield 4. One of a series of fourteen photographs supplied by Mr. F. R. Smith, Publicity Officer, 17th January, 1957. No. 4056. The modern equivalent of No. 4385 (which compare). Medium fitting work being carried on in conjunction with machining. Notice the maintenance of clear gangways, adequate lighting, a plentiful supply of working cranes and modern methods of stacking parts for inter-operational storage on both stillages and pallets.

PHO 13635

FILE PRINT

COPYRIGHT
OF
DAVY AND UNITED
ENGINEERING COMPANY
LIMITED

4056