

Copy invoice of Samuel Prudames, plumber, glazier and gas fitter

Publication/Creation

December 1874 - December 1875

Persistent URL

<https://wellcomecollection.org/works/xwgr7jxp>

License and attribution

Works in this archive created by or for The Retreat, York are available under a CC-BY-NC license. Please be aware that works in this archive created by other organisations and individuals are not covered under this license, and you should obtain any necessary permissions before copyright or adapting any such works.



Wellcome Collection
183 Euston Road
London NW1 2BE UK
T +44 (0)20 7611 8722
E library@wellcomecollection.org
<https://wellcomecollection.org>

The Committee of The Friends Meet at

6 LOW OUSEGATE

New York, Decr 1875

Dr. to Sam^l Prudames
Plumber Glazier and Gas Fitter,

1874			
Dec 8	1	Hose pipe repaired	12
12	1	Man 1/4 day fixing gas bracket & pipes in Mr Woodheads room	4 6
	1	Cooka Shown double gas bracket	8 6
	1	Wood patcher, 1 elbow & screws to ditto	1 9
14	1	Man & Appren 1 day to ditto, gas pendant in mens gallery, ball tap in basement & clearing bath pipe in 6 th gallery towards end	8
	1	Foot 6. 3/8 brass tube, 1 wood patcher & 2 joints	2 6
	1	New stalk & 1 new washer repairing ball tap	1 6
	1	New leather to W.C. valve & 4 new burners in 2 nd & 3 rd gallery mens end	1 8
22	1	Sho Patchy	2 6
29	1	Man 1 day & Appren W.C. pipes 9 th fall east end & ditto Mr Deans gallery	6
	1	Joint to water pipe, 1 joint to pendant tap corridor & wire to W.C.	2 3
1875			
Jan 6	1	Man & Appren 10 hrs repg pipes in mens roof 2 nd gallery, bathroom long corridor & fixing hot water tap in female gallery	9 2
	1	1/2 in Best gun metal hot water tap	8 6
7	1	Man 10 hours & Appren 3 hrs repairing pipes in roof 3 rd gallery bath room, Mr Woodrass's room & W.C. at Lodge	8 4
	4	Sts. 1/2 in lead water pipe & 6 joints	1 3 10
	10	1 in lead pipe & 2 joints to W.C.	4 11
	1	1 in joint & 6 hooks to hot water pipe in roof	1 6
	1	Sq 31 x 26 in picture 3/8 & 1 Sq 19 x 15 1/2 in ditto 1/4	5
8	1	Man & Appren 10 hrs repg water pipes in top corridor, back cellar	9 2
	3	Sts. 1/2 in lead water pipe & 7 joints to ditto	1 1
	1	New leather to W.C. valve & 2 feet new copper wire	1 3
9	1	Man 10 hours repg water pipe at Lodge W.C. & clearing wash basin	4 6
	5	joints to water pipe, 1 new washer to ball tap & new wire to W.C.	7 3
18	1	Man & Appren 10 hours repairing water pipe to stable, W.C. at Lodge & fixing wash basin in Saloon	9 2
	2	joints to water pipe in stable	2 6
		Carried forward	8 10 3

		Amount not forward		8	10	3
1875 Jan 18	1 New white basin to W.C. at Lodge			12	6	
	1 joint to W.C. pipe, putty & wire fixing basin			3		
	1. New marble wash basin with head & overflow			10	6	
	19	1 Man 10 hrs repairing pipe in enormous Court yard, W.C. in S. garden clearing around in 3 rd gallery, gas bracket in 9 th fall cante & Lodge		7	6	
		6" Lead pipe & 2 joints for Court yard		4	3	
		1 New spring for pendant in Dining room		1	3	
		Solder repairing pendant & 1 new washer to W.C. valve		1	3	
		1. 3/8 gas tap for Mr Briggs room		1		
Feb. 12		1 Plain ground moon.		1		
23		1 Man 10 hours repairing pipe to Lodge wash basin, tap in Scullery and gas pendant in top Corridor		7	6	
		4 1/2" 3/4 in Lead pipe & 3 joints to ditto		5	3	
		1 New washer to Steam boiler tap		1		
		Solder for repairing pendant & pipe & 2 new gas burners		1		
Mar 5		1 Sq 14 1/8 x 13 1/2 for picture		1		
8		1 Man & Appren 10 hours repairing water in South East wing W.C. near glass door, ball tap 1 st gallery Kitchen & taps in 3 gallery		9	2	
		1. 3/4 Best plug stop tap South East wing		6	6	
		3" 3/4 in Lead pipe & 2 joints to ditto & 1 new washer to ball tap		3	10 1/2	
		1 New leather to W.C. valve, 1 Crank & Copper wire		2	3	
9		1 Man & Appren 10 hours repairing Spout & pump at Lodge		9	2	
		8" 1 in Lead pipe to hot water pipe in Kitchen		2	4	
		3 joints to ditto & One 1 1/2 in joint to pipe in Lodge cellar		6	6	
		1 New washer to tap on Kitchen sink			6	
11		1 Man 5 hours addressing Mr. Taylor with water pipes		3	9	
13		1 Sto Putty		2	6	
24		1 Man & Appren 10 hours repairing pipe in Court yard, casting sinks in Mr Deans gallery & gas in waiting room		9	2	
		1 joint to pipe in Court yard		1	3	
		1 Sto 5 Sheet Lead for sinks		5	1 1/2	
		15 Feet. 3/8 in Lead gas pipe, 1 foot Brass tube & 1 wood bracket		4		
26		1 Man & Appren 10 hours fixing gas in cracking & rep. water & pump 1 joint to pipe in larder		9	2	
				1	3	

Carried forward.

15 4 9

1875

Amount brot forward

15 4 9

Mar 29

1 Man & Appren 13 hours fixing Chandelier in waiting room, repairing
pipe in garden & clearing pipe in 6th gallery 13th room

11 11

1. 3 Light bronze Chandelier

2 15

3 Star Cut gas moons for ditto

4 6

1 New washer to tap in Kitchen garden, 1 joint to pipe for fountain in Drd garden

1 9

30

1 Man 10 hours clearing trap in 3rd gallery Kitchen sink, repairing

ball tap to cistern in roof & clearing sink in South East wing

7 6

1. 2 in Ripston trap in 3rd gallery

7 6

1 Large washer to ball tap & 1/2^{lb} solder to pipe.

2

Apr 12

1 Man & Appren 10 hours repairing gas in M^{rs} Dean gallery and
terminat in long corridor South East wing.

9 2

3rd Solder to pipes & 1 joint to gas pendant.

3

26th 11th 1/2 in Lead pipe for supplying cistern in Cuth roof

5 9 4 1/2

8 S^{ts} 3rd Sheet lead.

1 10 10

13

1 Man & Appren 10 hours fixing pump pipe in cellar & clearing pipe
in 3 gallery sink

9 2

1. 1/2 in plumbing joint to pipe in cellar

2

14

1 Man & Appren 10 hours repairing pipe W.C. in refectory, Court yard,
water pipe at Stables & pump

9 2

1 New leather to W.C. valve & new Copper wire

1 6

1 New valve to manure pump

2 6

2 Large hooks to pump pipe & 1 joint to pipe in Stable

3 3

15

1 Man & Appren 10 hours making & fixing overflow to top cistern
and fixing ball tap

9 2

1. 2 in Lamberts patent ball taps & ball

2 12

1st Solder to overflow

1 3

16

1 Man & Appren 10 hours fixing ball tap & overflow to cistern

9 2

4th Solder to overflow 3rd & 2nd 1/2 in plumbing joints to pump pipe

9

17

1 Man & Appren 7 hours repairing pipe in roof, gas pendant in
Long Corridor & W.C. in basement.

6 5

1. 1/2 in joint to pipe in cellar & 1. 3/4 joint to pipe in roof

3 3

New packing to gas pendant & Copper wire to W.C.

1

19

1 Man & Appren 10 hours fixing gas bracket in Masons room and
clearing W.C. in 9th female gallery

9 2

30 Feb 3/4 Lead gas pipe & 1 dozen hooks

5 3

Carried forward.

34 0 6 1/2

[Faint, illegible handwriting on lined paper, likely bleed-through from the reverse side. The text is organized into several paragraphs across the page.]

Dr to Sam^l Prudames

Plumber Glazier and Gas Fitter,

1873-	Amount list forwarded.	Oct	0	6 $\frac{1}{2}$
Apr. 19	1 Wood patter, 1 brass elbow, screws & 4 joints	3		
20	1 Man & Appren 10 hours fixing iron water pipe to center roof & W.C. 9 th gallery } 5 Lengths - 2 in Cast iron water pipe. 1. 3 in Cast iron tee & 3 in Cast iron socket	9	2	
	1 New leather to W.C. valve & new copper cover to ditto	15		
	1 Man & Appren 10 hours fixing ditto to pump	12	6	
21	1 Man & Appren 10 hours fixing S. Trap to sink at Coachman's house & repairing W.C. in South East wing } 1. 3 in S. Trap, 1 brass cleaning screw & 20 Cts fixing 1. 4 in brass grate & 3. 2 in joints to trap 1 New leather to W.C. valve	9	2	
22	1 Man & Appren 10 hours repairing W.C. & ball taps } 4 New washers to taps, 3 new leathers & 3 feet wire to W.C. & 1 joint to gas pond and	10	6	
23	1 Man & Appren 5 hours in roof male end & W.C. in 4 th gallery } 1. joint to pipe in roof	9	2	
26	1 Man & Appren 10 hours taking down & repairing Chandeliers in dining room } 20 Feet 3/4 in lead gas pipe & 1 foot 6. 3/8 brass tube 1 Wood patter & screws, 3 joints & 6 hooks	4	7	
May 5	1 Man 10 hours repairing pipe & bath in 5 th gallery & ball tap to } tee pipe in Scullery 1 New washer to ball tap & new coil to W.C. in Centre 4 1/2 Lead pipe & 2 joints to bath	1	3	
6	1 Man & Appren 10 hours fixing wash basin, repairing W.C. in } Mrs Deans gallery & hot water pipe in roof. 1. 12 in White basin in 5 th gallery & partly fixing 1 st Fine solder repairing trap to W.C.	9	2	
26	1 Man & Appren 10 hours to ditto & hot water pipes } Carried forward	4	6	
27		3	10	
		9	2	
		41	9	4 $\frac{1}{2}$

1875	Amount sent forward	41	9	42
May 27	1. 1 in brass union & 2. 1 in bosses to pipes in roof	5	6	
	1. 1 in plumbing joint to ditto	1	6	
	1. Copper bowl to W C in Mrs Deans gallery	4	6	
	1 Marble basin for Doctors W C	12		
	1. New screw bit tap with boss for Coachmans house	6	6	
	6 Sgs 1 1/4 x 9 ordered by the Baker	3		
28	1 Man & Appren 10 hours fixing W C in Mrs Deans gallery	9	2	
	Putty & wire to ditto 1/4 & 1 new leather to W C valve in female bathroom	2		
	3" Lead pipe & 2 joints to Coachmans house	3	4	2
	1 Sto Putty	2	6	
June 4	4 Sgs perforated zinc 21 3/4 x 15 3/4	5		
10	1 Sg. 16 sq sheet glass 17 1/4 x 13 3/8	1		
	1 Man 7 hours & 1 man 6 hours glazing door & fanlight	9	9	
	1 Sg embossed plate glass 49 3/4 x 31 1/2 in door	12	16	42
	2 Sgs ditto 49 3/4 x 12 each side of ditto			
	1 Sg ditto 38 1/2 x 33 1/4 in fanlight			
	2 Sgs ditto 38 1/2 x 12 each side of ditto			
28	1 Man & Appren 8 hours repairing taps in W C.	2	4	
	Half quarter cement to tap in No 1 gallery & 1 joint	2	6	
	1 New leather to W C valve & new wire to No 4 gallery	1	6	
	1 New washer to hot water tap in Scullery	1		
July 6	Labor repairing Chandelier in Mrs Deans gallery	1	6	
7	1 Man 10 hours fixing gas bracket in 1st gallery	4	6	
	18 Fat. 3/4 in lead gas pipe & 4 joints	4	6	
	1 brass elbow, screw, 13 hooks & solder to Chandelier	1	6	
9	Labor taking down Chandelier in Large dining room	1	6	
10	1 Man 5 hours repairing Chandelier and 1 brass nipple	4		
	2 Sgs bright fluted glass 10 1/2 x 10 1/2 in passage door	3		
14	Labor taking down gas fittings	2		
15	1 Man & Appren 12 hours taking down gas fittings, W C & pipes	11		
16	1 Man & Appren 12 hours taking off old lead & pipes at Large	11		
17	1 Man & Appren 7 hours to ditto	6	3	
19	1 Man & Appren 10 hours to ditto & taking up bath	9	2	
22	2 Men 4 hours taking lead off roof	6		
	1 Man 7 hrs fixing glass Chandelier for Mr Granen & 3 joints to ditto.	6	9	
	Carried forward	62	2	82

1875

62 2 8⁵

July 23 2 Men & Appren 5 hours taking off old lead

8 4

26 1 Man 7 hours taking out cistern & lead gutters

5 3

27 1 Man 10 hours to ditto

1 6

28 1 Appren 10 hours taking lead off roof

5

Aug 4 1 Man & Appren 6 hours repg W.C & water pipe N^o 1 gallery in Area
10" 1 in Lead pipe, 2 joints & 2 feet off set cover.

5 6

6

5 1 Man & Appren 10 hours & 1 man 5 hours cutting trench & laying out
pipe in field

12 11

11 Sto Dr. 2 1/4 Lead pipe & 2 joints

2 8 7

6 1 Man & Appren 10 hours repairing cistern in field, fixing tap & hose
pipe in stable yard & gutters in N^o 1 gallery

9 2

1. 1/2 in Lamberts patent bib tap & 1 joint

1 9

1 Sto shut lead & 1" fine solder to cistern

5 3

1 New washer to tap in stable yard

6

1 joint to hose pipe & 2" solder to gutters

3 6

2 Sg. 9 x 8 in Clerk of works Office

1

12 1 Man 10 hours repairing Windows

1 6

1/2 Putty to ditto 1/3 & 1 Sq 28 1/2 + 22 for picture 2/3

3 6

1 Man & Appren 10 hours repg W.C in 3rd garden & gas pendant M^{rs} Mans N^o 4 gal

9 2

2 New washers to patent valve to W.C

2

1 New burner & 1 new elbow with gallery for gas

1

14 1 Man 7 hours repairing hot water in N^o 1 gallery, fixing pipe & gas
fittings for M^{rs} Begg's room

5 3

1 joint to hot water pipe

1

1 Double bronze gas bracket

9 6

1 Wood pattern, 1 elbow, screws & 2 joints to ditto

2 2

1 pillar & gallery for gas

9

16 1 Man & Appren 10 hours repairing windows

9 2

1/2 Putty to ditto

1 3

19 1 Man & Appren 3 hours examining pipes & cistern in 3rd gallery

2 9

26 1 Man 3 hours repairing W.C at M^{rs} Leathons

2 3

Seps 1 1 Man & Appren 10 hours & Appren 4 hours repairing windows

10 6

2 1 Man & Appren 10 hours repairing water pipe & basin in cellar

9 2

10 Feet 1/2 in lead water pipe, 3 joints & 4 hooks to ditto

9 1

1. 1/2 in bib tap.

4 6

Carried forward.

72 19 5⁵



Dr to Sam^l Prudames

Plumber Glazier and Gas Fitter,

1875.	Amount brot forward	72	19	5 $\frac{1}{2}$
Sep. 2	1. New joint to pipe in Engine House		1	3
7	1 Man & Appren 10 hours repairing W.C., clearing bath pipe & forcing stop taps		9	2
	1. New plug stop tap		6	
	2 joints to ditto.		2	6
	1. 3 in S. Trap & 1. 2 in brass cleansing screw & 1. 4 in brass grate		12	
9	1 Man 11 hours repairing valve to Doctors W.C., forcing traps to sink & repairing water pipe in basement.		8	3
	1. 3 in - 1. 2 in & 1. 1/2 in joints to ditto		6	
16	1 Man & Appren 10 hrs repairing ball taps in basement, roof & W.C.		9	2
	1 st Solder repairing roof		1	3
	1 Piece sheet India rubber to ball taps in basement		1	
	2 New washers to ball taps W.C. in ditto		1	
17	1 Man & Appren 10 hours repairing ball taps to large cistern in roof pipe in Court yard, W.C. cistern & pipe in basement. Women's end		9	2
	1 Large India rubber washer to tap in roof		1	
	1 joint to water pipe in Court yard		1	3
	1 New stalk & washer to ball taps in basement		1	6
	1 New leather & new copper wire to W.C.		1	3
	1 Man & Appren 10 hours repairing pipe in dead house & forcing Belliard room lamp		9	2
	1 Belliard room lamp	7	7	
	20 Feet 1/2 in lead gas pipe & 4 foot 3/8 in ditto		10	6
	1 Large wood pattern & screws to ditto		2	6
	3 Feet 1/2 in lead water pipe, 2 joints & 2 hooks		5	3
22	1 Man & Appren 10 forcing pipes to belliard room light & cutting roads to fix new pipes to ditto		9	2
23.	1 Man & Appren 10 hours forcing pipe to ditto, repairing tank pump in garden & glazing		9	2
	Carried forward.	86	3	11 $\frac{1}{2}$

1875	Amount bot forward	86	3	11½
Sep 23	46 Feet ½ in lead gas pipe, 6 joints & 6 hooks	1	13	
	1. 6 in Flange leather to manure pump		2	6
	1 New leather to bucket & 3 in iron bolt		2	
	1 Gutta serena joint to hose pipe		1	
Oct 4	1 Man 6 hours repairing Cistern in N ^o 2 gallery		4	6
	2 Sq 25 ¾ + 2 ½ best 16 g sheet for Picture		3	9
	2 Sq 28 ¾ + 16 ¾ ditto ditto		3	2
6	1 Man & Appren 10 hours repairing Cistern & Boys to bath		9	2
	4" Solder to ditto		5	
7	1 Man & Appren 10 hours to ditto & ball tap in 3 rd gallery		9	2
	5" Solder to Cistern & 1 new washer to ball tap		6	9
	1 Sq fluted 10 ½ + 8 ½ in Centre		1	
8	1 Man & Appren 10 hours repairing pipe in washhouse and fixing tap in Engine House		9	2
	1. 1/2 in Plug stop taps & 2 joints to boiler in Engine House		8	6
	2. 1/2 in strong lead pipe & 3 joints in washhouse		5	6
	1 New washer to ball tap to Cistern in basement			6
	1 Man 7 hours repairing water pipe in basement, fixing gas pipe in M ^{rs} Briggs Room & cleaning out filter for Doctor's House		5	3
	1. 1/2 in joint to water pipe & 4 joints to gas pipe		2	
14	1 Man & Appren 10 hours repairing Chandelier in dining room, & fixing bracket in Centre, packing valve in yard & upy felt pipe garden hose		9	2
	4 New harness to gas bracket & new packing to valve		2	
	1 Slo Putty		2	6
27	1 Man & Appren 10 hours repairing Urinal & water pipe 2 nd gallery & water pipe in M ^{rs} Deans gallery washhouse		9	2
	6" ¾ lead pipe & 3 joints in washhouse		4	3
	1" Solder repairing pipe & 1 new burner to gas M ^{rs} Deans		1	6
Nov 12	Later repairing window & 1 sq 12 + 8 in bath room		1	6
	1 Sq 17 + 18 in Doctors Nursery		1	8
17	1 Man 8 hours repairing pipe in 2 nd gallery & gas in 3 rd gallery room		6	
	1 Foot 6 in ½ in water pipe & 2 joints		2	10½
	1" Solder to repairing pipe in 2 nd gallery Kitchen		1	3
26	1 Man & Appren 10 hours clearing rising main to Cistern in tomeny roof, pipe to overflow in mens roof & wash pipe in 5 th gallery		9	2
	Carried forward		94	6 11

1875
In 26
In 14

13

115	1875-	Amount bot forward	94	6	11
6	Nov 26	$\frac{1}{2}$ " Four Solder & 1 new-washer to tap at stable		1	3
	Dec 14	1 Man & Appren 10 hours clearing urnals in 3 gallery and pendants in 3 rd & 6 th galleries		9	2
6	15	1 Man & Appren 7 hours repairing water pipe & ball tap in No 1 Area & 1 st Solder to ditto		7	8
9	20	1 Man & Appren 10 hours repairing gas in 9 th gallery, pendant in Mrs Deans gallery, fixing pipe & bracket in Mr Nicholsons room and ball tap in basement		9	2
2		1 joint to pendant, 1 washer to ball & 1 burner to gas		1	9
9		1 Double bronze gas bracket		8	6
2		1 Wood pattern, 1 brass elbow & screws		2	
9		20 Feet $\frac{3}{8}$ gas pipe, 3 joints & 12 hooks		5	6
2	21	1 Man & Appren 9 hours & washer to hot water tap in basement		9	3
1		1 New washer to tap & 1 joint to pendant in Long Corridor		1	6
1		25 Feet $\frac{3}{8}$ Lead pipe, 18 hooks & 3 joints		6	8
6	22	1 Man & Appren 10 hours fixing bracket in billiard & clearing sink		9	2
3		1 Bronze double gas bracket		8	6
		24 Feet $\frac{3}{8}$ Lead pipe, 3 joints & 14 hooks		6	2
		1 Wood pattern, 1 elbow & 1 plain moon		2	6
2	23	1 Man & Appren 10 hours fixing water pipe to billiard room W C		9	2
6		30 Feet $\frac{1}{2}$ in Lead water pipe		17	6
2		1. $\frac{1}{2}$ in patent ball tap & ball		2	
6	24	1 Man & Appren 10 hours laying & cutting roads for water pipe to billiard room		9	2
2		24 Feet $\frac{1}{2}$ in Lead water pipe & 2 joints		16	
3	27	1 Man 10 hours fixing ditto, clearing out cistern & repairing gas in Mrs Deans gallery		7	6
6		10 Feet $\frac{1}{2}$ in Lead pipe, 1 joint & 12 hooks to W C		7	7
6		1 joint to gas fitting Mrs Deans gallery			6
8	28	1 Man & Appren 10 hours rep & fixing pipe to W C for billiard room		9	2
10		3 joints to pipes & 4 hooks		3	3
3		2 New bathed to W C valve & 6 feet new Copper wire		2	9
2	29	1 Man & Appren 10 hours fixing water pipe to supply W.C. cistern in billiard room & repairing W C in 1 st gallery		9	2
11		1 joint to water pipe in Scullery		1	3
		Carried forward	103	15	8

1875	Amount list forward	103. 15. 8
Dec. 29.	1 New washer to ball tap to boiler feedet	6
	Copper wire to repairing ball tap in billiard room	6
Dec. 30.	1 Man 1 Appren 10 hours repairing W. C. in 1 st gallery, gas in 3 rd gallery & focusing glass in 2 nd & 3 rd gallery. among Cante }	9. 2
	1 W. C. cleaned & refilled 6/4 1 New Copper bowl to ditto 6/4	12. 6
	Putty & Copper wire to re focusing ditto	1.
	1 Joint to re focusing ventilating pipe	1. 3
31.	1 Man 1 Appren 10 hours repairing Chandeliers in D. drawing room } repairing W. C. in billiard room & covering trap door to Ashen on flat to ditto	9. 2
	1 3/4 Joint to repairing pipe in Chandeliers	1. 3
	1 W. C. refilled 6/4 1 New Copper bowl to ditto 6/4	12. 6
	Putty & wire to re focusing ditto	1.
	3 Sls 7" Sheet lead for trap door	13. - 1 1/2
	1" Solder to ditto	1. 3

L 106. 18. 10 1/2



Purdans,
106. 18. 10.